

Bridgeboro Historic District  
J. S. Lowden House  
Route 130, Section F Parcel 16  
Bridgeboro  
Burlington County  
NJ

HABS No. NJ-899-11

HABS  
NJ  
3-BRIBO,  
1/11-

PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDING SURVEY  
NATIONAL PARK SERVICE  
DEPARTMENT OF THE INTERIOR  
WASHINGTON DC, 20240

STATE New Jersey	COUNTY Burlington	TOWN OR VICINITY Bridgeboro-Delran Townships
HISTORIC NAME OF STRUCTURE (INCLUDE SOURCE FOR NAME) J. S. Lowden House (1860 Lake & Beers Map of Burlington County). Bridgeboro Historic District		HABS NO. NJ-899-11
SECONDARY OR COMMON NAMES OF STRUCTURE Maudean Keys House		
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES) Route 130, Bridgeboro - Route 130, Section 9F Parcel 160		
DATE OF CONSTRUCTION (INCLUDE SOURCE) Before 1860 (1860 Map of Lake & Beers)	ARCHITECT(S) (INCLUDE SOURCE) Unknown	
SIGNIFICANCE (ARCHITECTURAL AND HISTORICAL, INCLUDE ORIGINAL USE OF STRUCTURE) Part of the Bridgeboro Historic District; a property determined eligible for inclusion to the National Register by the Keeper of the National Register on 6/26/81. The Bridgeboro Historic District is significant as the most cohesive concentration of 19th century buildings in Bridgeboro. (House is a residence of J. S. Lowden.)		
STYLE (IF APPROPRIATE) Vernacular		
MATERIAL OF CONSTRUCTION (INCLUDE STRUCTURAL SYSTEMS) 2 story wood frame dwelling with asphalt shingle siding		
SHAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE) The rectangular 2 bay 2½ story side hall with entrance door in northern bay is approximately 14½ feet wide by 24 feet in depth. A 1 story lean-to kitchen addition 18 feet		
EXTERIOR FEATURES OF NOTE wide by 10 feet deep is attached to the rear.  No noteworthy exterior conditions exist due to its present vandalized condition upon inspection on 8/23/82.		
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED) Two-room deep plan with living room (front) and dining room (rear) bisected by a fireplace with wraparound pie-shaped staircase. Lean-to kitchen to rear of dining room. The second floor consists of 2 bedrooms. No interior features of note.		
MAJOR ALTERATIONS AND ADDITIONS WITH DATES Not applicable.		
PRESENT CONDITION AND USE Presently vacated since 10/80. Condition is extremely poor and dilapidated.		
OTHER INFORMATION AS APPROPRIATE		
SOURCES OF INFORMATION (INCLUDE LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.) Cultural Resource Survey for Rt. 130, 9F, 2/80, by Historic Sites Research. Real estate appraisal 9/24/79 and interior inspection on 8/23/82. Determination of Eligibility on 6/26/81.		
COMPILER, AFFILIATION Dennis DeGregory, N. J. Department of Transportation		DATE 9/30/82